



MDL Reference Number:	1.1	
Document Number & Revision:	CHS76-71-002 ACD Rev NC	


Document Title:	Approval Control Document
Document Source:	DAO 92-V-01
DAO Project Number:	CHS76-71-002
Project Title:	Cowling Oil Door, Closing Spring
ATA Code:	71

Applicability	
Aircraft MFG. & Model	Registration (Serial Number)
S76 Series	N/A



Drawing Change Notice			
#	Date	Description	Signature
1			
2			
3			
4			
5			

Revision Record					
Rev.	Date	Description	Function	Name	Signature
NC	22 June, 2005	Initial Issue	Prepared - Structures	G. Hatton	
			Checked - Structures	B. Olsen	

MDL Reference Number:	1.1	
Document Number & Revision:	CHS76-71-002 ACD Rev NC	

Master Document List					
Item #	Source	Title / Subject	Document Number	Rev	Date
<b>1 - Certification</b>					
1.1	DAO 92-V-01	Approval Control Document	CHS76-71-002 ACD	NC	22 June, 2005
<b>2 - Installation</b>					
2.1	DAO 92-V-01	Installation Drawings	CHS76-71-002	NC	22 June, 2005
2.2	DAO 92-V-01	Parts Data List	CHS76-71-002 PDL	NC	22 June, 2005

**NOTICE:**

This modification is a "Minor" since none of the criteria noted within CAR 571 Appendix A are affected. This modification is to be installed in accordance with AC43.13-1B, CH4, Sect 4, Ch 6, Sect 1, 3 & 4 and AC43.13-2A, Ch 1, Para 4-10.